Oil Field Environmental Incident Summary

Incident: 20140609171543 Date/Time of Notice: 06/09/2014 17:15

Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Name: PARRISH 1-31H

Field Name: PERSHING Well File #: 17371

Date Incident: 6/9/2014 Time Incident: 10:40 Facility ID Number:

County: MCKENZIE Twp: 150 Rng: 96 Sec: 31 Qtr: NE SE

Location Description: Immediately adjacent to the Northe east side of the well pad.

Submitted By: Lewis Schoenberger Received By:

Contact Person: Lewis Schoenberger

PO BOX 51810

MIDLAND, TX 79710-1810

General Land Use: Pasture Affected Medium: Topsoil

Distance Nearest Occupied Building:0.5 MileDistance Nearest Water Well:0.5 Mile

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 10 Gallons

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 8/18/2016 Clean Up Concluded: 6/30/2014

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

Oil mist deposited on plants off of the Northeast side of the well pad.

Action Taken or Planned:

Oil impacted soil and debris on the pad will be collected for appropriate disposal. Oil impacted vegetation will be cut and collected for appropriate disposal.

Wastes Disposal Location: to be determined

Agencies Involved:

Updates

Date: 6/25/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an unspecified cause, sprayed on and off location. Followup is necessary to confirm adequate cleanup off location.

Date: 6/26/2014 Status: Inspection Author: Wax, Pete

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site 10:15 - off site 11:30. Overcast, no wind, 67 degrees. Incident appears to be overflow from tank battery. No puddles, but the soil is oily (took pictures). Nearly all of the oily material is on top (flat surface) of the well pad. What small volume that did get off pad did not appear to get beyond a short distance of the outside slope of the pad. Walked all the way around west and north side of pad and looked for signs beyond the pad base and could not find any. The nearest water is a natural seep and resulting drainage that has tributaries on both the north and west sides of the pad 150 feet and 300 feet away, respectively. Vegetation looked healthy, and there were lots of bugs swimming around. The drainage off the area of the pad (where the spill is) is in two locations: to the north 50 feet west of the NW corner of the pad, and to the west 30 feet south of the NW corner. There was a workover crew on site, and I talked with them about cleaning up the top to remove any risk of the remaining oil-impacted soil off site. They do not own the pad but would pass along the information.